## WAC LIGHTING

Responsible Lighting®


## CAUTION:


For Use with WAC "H" track systems. Fixture may also be used on other manufacturers brand of track (consult factory for compatibility).

CAUTION – To reduce the risk of a burn during relamping, remove from the track before relamping. Read all instructions before installing.

## **FIXTURE INSTALLATION**

- 1. Note the track has a groove running it's length to indicate polarity.
- 2. Insert adapter into track slot and rotate it 90° The embossed arrow on the adapter should point to the grooved side of the track.
- 3. Push up and turn the locking tab into the lock position.
- 4. Removal is the reverse procedure. Tracks may be positioned anywhere along the track length.





## **RE-LAMPING:**

- 1. Use appropriate protection when handling hot lamps.
- 2. Turn power off at main switch.
- 3. Unscrew lamp counterclockwise to remove.
- 4. For HTK-764-70E Use Par 30 metal halide lamp **70W only**.
- 5. For HTK-764-39E Use Par 30 metal halide lamp **39W only**.
- 6. Never operate a lamp that is chipped or damaged.
- 7. Installation is the reverse procedure.

**Note:** Metal halide lamps require several minutes of operation to reach full brightness. If power is interrupted lamps will take several minutes to re-strike. This is a normal characteristic of metal halide lamps.

**WAC Lighting** www.waclighting.com Phone (800) 526.2588 • Fax (800) 526.2585 Headquarters/Eastern Distribution Center 44 Harbor Park Drive • Port Washington, NY 11050 Phone (516) 515.5000 • Fax (516) 515.5050 **Western Distribution Center** 1750 Archibald Ave • Ontario, CA 91761 Phone (800) 526.2588 • Fax (800) 526.2585