

INSTALLATION INSTRUCTION
Line Voltage - Clamp Mount Spot Lights
DL-188

WAC LIGHTING
Responsible Lighting®

SAFETY INSTRUCTION


WARNING – To reduce the risk of FIRE, ELECTRIC SHOCK, EXPOSURE TO EXCESSIVE UV RADIATION, and OR INJURY TO PERSONS:

- Turn off/unplug and allow cooling before replacing bulb (lamp).
- Bulb (lamp) gets HOT quickly! Only contact switch/plug when turning on.
- Do not touch hot lens, or guard.
- Do not remain in light if skin feels warm.
- Do not look directly at lighted lamp.
- Keep lamp away from materials that may burn.
- Use only with a 50-watt or smaller bulb (lamp).
- Do not touch the bulb (lamp) at any time. Use a soft cloth. Oil from skin may damage bulb (lamp).
- Do not operate the luminaire with a missing guard.

SAVE THESE INSTRUCTIONS

INSTALLING:

1. This display light is designed to be secured on a flat surface. It is supplied with a cord and plug.
2. It will be necessary to drill a hole not less than 51mm in diameter and not more than 55mm. The hole should be positioned on the top of the display pillar in the center of the mounting surface.
3. Once this is completed, thread the plug through the hole. Make sure the bracket is positioned so that the slotted holes in the bracket are over a solid wood area. Secure the bracket to the mounting surface with screws provided.
4. Slide the cover piece over the bracket and secure it to the mounting bracket using the single machine screw.
5. Adjust fixtures as needed. Plug power cord to an outlet. Assembly is complete.



WAC Lighting
www.waclighting.com
Phone (800) 526.2588 • Fax (800) 526.2585

Headquarters/Eastern Distribution Center
44 Harbor Park Drive • Port Washington, NY 11050
Phone (516) 515.5000 • Fax (516) 515.5050

Western Distribution Center
1750 Archibald Ave • Ontario, CA 91761
Phone (800) 526.2588 • Fax (800) 526.2585