

Installation Instructions: Metal Halide Track Fixture – LARC Series

Models: JTK-HID330-39E & JTK-HID330-70E


CAUTION:

For Use with WAC J" & "J2" track systems. Fixture may also be used on other manufacturers brand of track (consult factory for compatibility).

CAUTION – To reduce the risk of a burn during relamping, remove from the track before relamping. Read all instructions before installing.

Installing on Track:

1. Note the track has a groove running its length to indicate polarity.
2. Insert adapter into track slot and rotate it 90° the embossed arrow on the adapter should point to the grooved side of the track.
3. Push up and turn the locking tab into the lock position.
4. Removal is the reverse procedure. Tracks may be positioned anywhere along the track length.
5. Vertical and horizontal aiming have push lock buttons to secure settings.



Re-Lamping:

1. Use appropriate protection when handling hot lamps.
2. Turn power off at main switch.
3. Turn lens cap assembly counter clockwise to remove.
4. Turn lamp counterclockwise to remove.
5. For JTK-HID330-39E
Use Par 30 metal halide lamp 39W only.
For JTK-HID330-70E
Use Par 30 Metal halide lamp 70W only.
6. Never operate a lamp that is chipped or damaged.
7. Installation is the reverse procedure.

Note: Metal halide lamps require several minutes of operation to reach full brightness. If power is interrupted lamps will take several minutes to re-strike. This is a normal characteristic of metal halide lamps.