

## INSTALLATION INSTRUCTION

### Line Voltage - Clamp Mount Spot Lights

DL-150

WAC LIGHTING

Responsible Lighting®

#### SAFETY INSTRUCTION

WARNING – To reduce the risk of FIRE, ELECTRIC SHOCK, EXPOSURE TO EXCESSIVE UV RADIATION, and OR INJURY TO PERSONS:

- Turn off/unplug and allow cooling before replacing bulb (lamp).
- Bulb (lamp) gets HOT quickly! Only contact switch/plug when turning on.
- Do not touch hot lens, or guard.
- Do not remain in light if skin feels warm.
- Do not look directly at lighted lamp.
- Keep lamp away from materials that may burn.
- Use only with a 50-watt or smaller bulb (lamp).
- Do not touch the bulb (lamp) at any time. Use a soft cloth. Oil from skin may damage bulb (lamp).
- Do not operate the luminaire with a missing guard.

#### SAVE THESE INSTRUCTIONS

#### INSTALLING LAMP:

1. Use a 120v J-200-S 200 Watt Max (included)
2. Align lamp pins with socket holes and gently press in.
3. Place Clear glass lens over lamp and secure with retaining ring.

#### INSTALLING CLAMP:

1. Installs on a firm flat surface, such as wood, particleboard, cubicle partition etc. Standard clamp accommodates surfaces ½" to 2 1/2" wide.
2. Use the angle adjustment knob on the side to change the angle.
3. Adjust the height by sliding the telescoping rod.

#### ACCESSORIES:

1. Supplied with standard clamp that opens to 2 ½' wide.
2. An optional "DLC-4" clamp opens to 4".
3. An optional DLC-P clamp works on 2 1/2" pipe
4. Fixture supplied with clear glass lens. Maybe substituted with various accessory lenses consult catalog for compatibility.

---

#### WAC Lighting

www.waclighting.com

Phone (800) 526.2588 • Fax (800) 526.2585

#### Headquarters/Eastern Distribution Center

44 Harbor Park Drive • Port Washington, NY 11050

Phone (516) 515.5000 • Fax (516) 515.5050

#### Western Distribution Center

1750 Archibald Ave • Ontario, CA 91761

Phone (800) 526.2588 • Fax (800) 526.2585